

City of Watauga's
Open Records Request

Start date
Month of September, 2018

Case Type	Case Description	Initial Inspection Date	Short Address
Address	The address is required to be visible at the location.	09/05/2018	5924 Haney Dr.
Address	The address is required to be visible at the location.	09/05/2018	5916 Haney Dr.
Address	The address is required to be visible at the location.	09/05/2018	5865 Haney Dr.
Address	The address is required to be visible at the location.	09/06/2018	6001 Ridgecrest Dr.
Address	The address is required to be visible at the location.	09/07/2018	6109 Mackneal Trl.
Address	The address is required to be visible at the location.	09/12/2018	6501 Lampe Dr.
Address	The address is required to be visible at the location.	09/12/2018	6512 Lampe Dr.
Address	The address is required to be visible at the location.	09/12/2018	6500 Lampe Dr.
Address	The address is required to be visible at the location.	09/13/2018	5533 Spring Ridge Dr.
Address	The address is required to be visible at the location.	09/14/2018	5365 Timber Ridge Dr.
Address	The address is required to be visible at the location.	09/20/2018	5648 Bonnie Dr.
Address	The address is required to be visible at the location.	09/24/2018	6432 Moonglow Ln.
Address	The address is required to be visible at the location.	09/26/2018	5608 Chesapeake
Address			

Total Cases: 13

Exterior Property Roof must be repaired. 09/07/2018 6305 Douglas Dr.

Exterior Property

Total Cases: 1

Exterior Structure	The garage door at 6208 North Park is damaged and needs repair.	09/11/2018	6208 North Park Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/06/2018	8005 Lazy Brook Dr.
Exterior Structure	Foundation must be repaired and maintained. Foundation is not supported by soil must have a maximum of 6 inches of exposed foundation. Roof must be repaired to support shingles and keep from leaking. Sheathing under shingles needs to be examined for rot and repaired correctly.	09/07/2018	6408 Dream Ln.
Exterior Structure	Concrete under window at front of driveway is not supported and must be repaired correctly. Steps under door leading to side yard must be repaired correctly. All broken items are a safety hazard and must be repaired.		
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/10/2018	6328 Patsy Ln.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/10/2018	6525 Highview Terr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/11/2018	6628 Levitt Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/11/2018	6652 North Park Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted. There cannot be any		6600 Lampe Dr.

	siding hanging from the structure.		
Exterior Structure	Broken windows must be repaired.	09/17/2018	6404 Dream Ln.
Exterior Structure	Broken window must be repaired.	09/17/2018	6409 Dream Ln.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/19/2018	5309 Cedar View Ct.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	09/28/2018	6941 Declaration St.

Exterior Structure

Total Cases: **12**

Hazardous Disposal of Waste	Paint may not be disposed of down storm drain. All dumped paint must be cleaned off curb and disposed of properly.	09/21/2018	6505 S Stardust S Dr.
-----------------------------	--	------------	-----------------------

Hazardous Disposal of Waste

Total Cases: **1**

Vacant Property High Weeds	Grass must remain under 12 inches at all times in the front and back yard. Grass is required to have weed eating and edging done around all sidewalks, fences and walls of the house. Grass may NOT be blown into street or left on the sidewalk. Grass must be disposed of properly. This is an annual notice, when found in violation a citation may be issued without notice.	09/12/2018	6608 Emily Dr.
Vacant Property High Weeds	Grass must remain under 12 inches at all times in the front and back yard. Grass is required to have weed eating and edging done around all sidewalks, fences and walls of the house. Grass may NOT be blown into street or left on the sidewalk. Grass must be disposed of properly. This is an annual notice, when found in violation a citation may be issued without notice.	09/13/2018	5928 Nanci Dr.
Vacant Property High Weeds		09/20/2018	6540 Avalon Dr.

Vacant Property High Weeds

Total Cases: **3**

Vacant Property Unsecure Property must remain secured when vacant. 09/24/2018 5909 Plum St.

Vacant Property Unsecure

Total Cases: **1**

Water Drainage All sewage drainage, including sink drains, should be clean, clear and maintained. Per Sec. 26-99 (a) All equipment should be maintained and work appropriately. 6728 Park Vista Blvd.
Bldg. 17
Suite # 1702

Water Drainage

Total Cases: **1**

TOTALS:	Total Cases:	32
----------------	--------------	-----------