



City of Watauga's  
**Open Records Request**

Start date  
 Month of November, 2015

Case Type	Case Description	Initial Inspection Date	Short Address
Exterior Property	House must be free of any broken windows	11/03/2015	6605 Oaklawn Dr.
Exterior Property	garage door must be free of any damage or broken windows	11/05/2015	5912 Bowling Dr.
Exterior Property			6308 Carousel Dr.
Exterior Property		11/17/2015	6200 Pine St.
Exterior Property	all chipped paint or exposed wood must be replaced or repainted and made weather resistant. all rotting wood must be replaced	11/19/2015	6220 Melinda Dr.
Exterior Property	all chipped paint or exposed wood must be replaced or repainted and made weather resistant. all rotting wood must be replaced	11/19/2015	6424 Melinda Ct.
Exterior Property	Property address must be visible from the street		
Exterior Property	all chipped paint or exposed wood must be replaced or repainted and made weather resistant. all rotting wood must be replaced	11/19/2015	6420 Melinda Ct.
Exterior Property	all chipped paint or exposed wood must be replaced or repainted and made weather resistant. all rotting wood must be replaced	11/19/2015	6416 Melinda Ct.
<b>Exterior Property</b>			
Total Cases:		<b>8</b>	
Exterior Structure	All rotted or exposed wood must be repaired or painted.	11/02/2015	5600 Lamar St.

Exterior Structure	All rotting and unpainted wood must be repaired or painted.	11/05/2015	6408 Saramac Dr.
Exterior Structure		11/06/2015	5721 Rosalyn Dr.
Exterior Structure		11/06/2015	6109 Pine St.
Exterior Structure			6604 Avalon Dr.
Exterior Structure		11/10/2015	7004 Constitution Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant.	11/13/2015	7920 Meadowbrook Dr.
Exterior Structure		11/17/2015	6424 Route 66
Exterior Structure		11/10/2015	6308 N Stardust Dr.
Exterior Structure	all chipped paint or exposed wood must be replaced or repainted and made weather resistant. all rotting wood must be replaced	11/19/2015	6533 Wooddale Dr.
Exterior Structure			6500 Patsy Ln.
Exterior Structure		11/19/2015	6913 Bernadine St.
Exterior Structure		11/19/2015	6437 Moonglow Ln.
Exterior Structure		11/19/2015	5748 Saramac Dr.
Exterior Structure		11/09/2015	6417 Dream Ln.
Exterior Structure		11/09/2015	6063 Shadydale Ct.
Exterior Structure		11/17/2015	6605 Nola Dr.
Exterior Structure			6412 Brookside Dr.
Exterior Structure		11/09/2015	6036 Judy Dr.
Exterior Structure		11/23/2015	6021 Kary Lynn Dr.
Exterior Structure		11/17/2015	5621 Travis St.
Exterior Structure	Both buildings on property in need of paint	11/25/2015	5625 Watauga

**Exterior Structure**

Total Cases: **22**

Vacant Property Maintenance		11/06/2015	5721 Rosalyn Dr.
Vacant Property Maintenance	all rotting or exposed wood must be replaced or repainted and made weather resistant	11/24/2015	7216 E Kary Lynn E Dr.

Clean out cap must be installed on clean out

**Vacant Property Maintenance**

Total Cases: **2**

Vacant Property Registration	Vacant property must be registered and maintained per city of Watauga ordinance. Please contact 817-514-5843 or 817-514-5839. To register property. You may also register property online at www.wataugatx.org.	11/02/2015	5600 Lamar St.
Vacant Property Registration		11/06/2015	5721 Rosalyn Dr.
Vacant Property Registration	Vacant property must be registered and maintained per City of Watauga ordinance. Please contact 817-514-5843 or 817-514-5839 to register property. You may also register property online at www.wataugatx.org.	11/13/2015	5745 Bonnie
Vacant Property Registration	Vacant property must be registered and maintained per City of Watauga ordinance. Please contact 817-514-5843 or 817-514-5839 to register property. You may also register property online at www.wataugatx.org.	11/18/2015	5715 Linda

**Vacant Property Registration**

Total Cases: **4**

<b>TOTALS:</b>	Total Cases:	<b>36</b>
----------------	--------------	-----------